Landebr. 1505 43-9-27-508 The solor role of on his reserve tank cond flour for one hour and first. The legine failed first. the bliss was quickly follow: 20 by right below. Piler Dailed to recognize The trouble and, conse= quently, did not switch tanks in time & gre= went the severe of them summing drey. Her Unade a forced bouding in 2 fool of water.

(1)			ı.F.	ig	hte	er.	G	roup.(TE) AA	F	met on October 2, 1942,		
		ed the following:									Pohont B Pllitatt Out It		
	Place, date, and time of accident blanbadr, September 27, 1942 at 1505 4					r	(15) Pilo(16) Pilo	t (name s	and r	Atcham, ETOUSA			
(3)	Aircraft station	Atcham Org. 49.5	Sq.	AA	F			(17) Reg	. Army		Res., ext. duty_X Res., inactive		
		P-38F A. C. No. 4									Grad. cadet Student		
		rom contractor June 26, 1									• • • • • • • • • • • • • • • • • • •		
	집에 없는 아이를 가게 하는 때로 되어 있다. 나라는	5:05 Hours since overhaul				375		(18) 0-0	-assigne	d 4	9th Fighter Squadron, AAF		
								(10) Org	-attache	d for	r flying Same		
	(7) Engine model V-1710-53 V-1710-49 (19) org.—attached for flying Same (8) Engine A. C. No.'s (20) Regular duties assigned Pilot												
	I. O	o.'s L. 41- 23469 R. 41- 22646 R	. 0.								***************************************		
(9)	Extent of dama	ge to engine(a) L. I. A5. R. I. (A5.) R									ng and date Rated Pilot March 15/4. 950:00 Hours on this model 180		
(10)	Total engine ho	urs 5					(23) Hou	rs per mo	nth l	last 3 months		
L.O. L.I. 105:05 R. I. 105:05 R.O. (1) 30:00 (2) 40:00 (3) 20:													
(11)	Engine hours sir	ace overhaul	*****			-	,	24) Mod	ole flows	14	3 months (1) C-40A, P-38		
	L. O	L. I. New R. I. New B	0			•	,	24) MOG	ieis nown	mst	(3) P-38		
(12)	Purpose of flight	Llanbedr Time	140	0		•	0	25) Secu	re from F	dich	t Surgeon, if pilot error is a causal factor:		
(13)	Weather at time	of accident. (If weather was a c	ausa	l fe	acto		,	W	as there	any	physical or neuropsychic condition which		
(14)	attach copies	of weather report and forecast for	the	fli	ght.))		wo	ould in any	y way	y account for this accident? See or No. P		
		Hazy						the so	Yes", attach cident.	comp	plete statement of the condition and its bearing upon		
	6 V	XX					(26) Dam	age to pri	A.C.	property; KM or No Form No. 17, "Damage to property certificate."		
(27) =		RESULTS TO PERSONNEL	-	-	-			%	1 %	1 %	CAUSES		
	1				П	_		70	70	70			
	C Commonder	"DUTT" ENTER STMBOLS AS FOLLOWS: N-Navigator B-Bomber	A	В	-	D	3			-	Error of judgment,		
	P-Pilot	R-Radio operator E-Engineer X-Passenger G-Gunner PH-Photographer		Injury	injury		repr	/	PILOT		Poor technique,		
DUT			4	Ę	=	injury	8	PER-	ERROR		Disobedience of orders, Cf SC W		
	Name, rank, and	Army status, as; Regular Army, Res. ext., Res. inact., etc.	Patel	Major	Minor	No in	3	SONNEL	100	100	Miscellaneous,		
-R	Rober	t F. Elliott, 2nd Lt.	-		(X/	0	4	OTHER		Supervisory personnel,		
	O/ Reserve Extended Duty					1		100	PER- SONNEL		Maintenance personnel,		
		•				II		the second			Other personnel,		
						u					Fuel system,		
						V					Cooling system,		
				-	\vdash	7			-	-	Ignition system.		
			1	-		1	1	_		-	Lubrication system.		
					H	1			POWER		Engine structure,		
			-	-	-				PLANT	-	Propeller and propeller accessories,		
erombercados) - co			+	*****	-	\dashv				-	THE RESIDENCE OF THE PROPERTY		
			-	-	-	+	-		-	-	Engine control system,		
			\vdash	tellosei	-	-	-	/			Miscellaneous (specify),		
-			-	-	-	,	-	1		-	AV		
				_	-	4	-				Undetermined,		
_	-		-	_	1	1					Flight control system,		
				_	14						Movable surfaces,		
					-			MATÉ- RIEL			Stabilizing surfaces; struce, wires, and fittings,		
											Wings; struts, wires, and fitting.		
(Exp	plain any unsuccessfu	d parachute jump by attachment)				1			AIR-		Landing gear; struts, wires, fittings, and retract. mech.		
		NATURE							STRUC-		Wheels, tires, and brakes,		
		(Check one only)							TURE		Fuselage, engine mount and fittings,		
DAMAGE TO AIRCRAFT (Lese power plant)		A—Collisions in full flight with other aircraft, B—Collisions in full flight with objects other than aircraft, C—Spins or stalls following engine failure, D—Spins or stalls without engine failure,									Cowling, fairing, and fittings,		
											Tail wheel assembly and skid,		
							1				Miscellaneous (specify),		
											A control of the cont		
	NE.	(E (1)—Emergency forced landings,) 5 32 21					x .				Undetermined,		
-Com	plete wreck, (5x)E (2)—Ethergency forced landings, (35 23 34)					1		,		Handling qualities,			
	r overhaul, G—Take-off secidents,				+	-				uments,			
3-Majo					+					ellaneous e uipment (specify),			
	H-Taring accidents,					+	-						
-Majo	r replacement, I (1)—Fires in the air,				+				Weather,				
		I (2)—Fires on the ground,	der von sakken	-		+		MIS- CELLA-		Darkness,			
)—Mino	or damage,	N-Structural failure,						NEOUS		Airpe	ort or terrain,		
		X-Miscellaneous,								Other,			
I—No di	amage,	Y-Undetermined,				1				Unde	stermined,		
										-	A STATE OF THE PARTY OF THE PAR		
0	. (1	- 1 (10)-1	RI		T	R	I	CTED)		Industrial		

RESTRICTED

PILOT'S STATEMENT

On Sunday, September 27, 1942, I took off in P-38F airplane, AC #41-7677 at 1400 hours on a Tow Target Mission. I had difficulty retracting the landing gear due to having to use the emergency release in order to raise the landing gear lever. I took off on reserve gas tanks and climbed to 6000 feet going directly to the gunner. range. I flew the gunnery pattern in the usual manner with another ship fir'ig on the target. After 55 minutes the left engine lost power. I believed the cause to be in the propeller and attempted to correct it by using the manual propeller control. There was no change in engine operation. The left engine indicated 33 inches pressure and the RPM stayed around 2600. For these reasons I had no idea that the cause was lack of gasoline. I did not check my gasoline guages and did not change tanks. I decided that the best thing to do was to go in and land. I trimmed the ship for single engine flight, flew over the field at 1000 feet and dropped the target. I circled the field and began a landing approach. The right engine stopped just as the left had. I was then at 800 feet and about 2 miles from the field. I turned towards the beach and glided down. I undershot the beach and landed in about 2 feet of water. I later checked the gasoline selector switches and found that they were still set on reserve tanks. I now believe that the cause of the accident was running out of gas on reserve tanks. I had been flying for an hour and five minutes. There was no injury to personnel or private property.

> Robert 7. Ellist ROBERT F. ELLIOTT, 2nd Lieut., Air Corps.

It was carelessness in that the pilot should have switched from reserve to main tanks approximately 15 minutes after take-off and immediately prior to landing switched back to reserve tanks.

1. 1.8

(30) RECOMMENDATIONS:

None.

Each member of the Committee has read and understands A. C. Circular No. 15-14, A. R. 95-120, and N. A. C. A. Report No. 576.

The above statement and recommendations, and the classification and analysis shown on the reverse hereof, are the concensus of opinion of this Committee.

1	Signed TROY KEITH, Major, A.C.		Operatio	ns Offic	er.
	() : (France)	(Rank)		(Designation)	
	Signed WILLIAM B. FILMER, Capt.,	A.C.	M	(Designation)	
1	Mark Mounne		ss't Ope	rations	Officer
2 1000 5	(Name)			OPTION)	

(31) REMARKS AND RECOMMENDATIONS (accomplish only if this report is initiated at other than the home station):

Data Ci-time	
Station Date Signature	

(32) REMARKS AND RECOMMENDATIONS:

I concur in the analysis and recommendations of the above Aircraft Accident Classification Committee. The necessary disciplinary action has been taken.

Enclosures (line cut those not applicable): Airplane (Airship) Flight Report.	Station Atcham, ETOUSA, Date October 3, 1942.
Uncatisfactory Report.	Signature THATER S. OLDS. Colonel, Air Corp.
Certificates of principal witnesses. List of damaged parts.	Signature THATER S. OLDS, Colonel, Air Corp.

RESTRICTED

(28) PILOY'S STATEMENT (state how the accident occurred, giving all details as to conditions, causes, and influencing factors):

See attached statement.

	Signature Pilot.
(29) STATEMENT OF A CIDENT CLASSIFICATION COMMITTEE (give comp	plete causal statement, amplifying the pilot's statement where necessary

Failure of the pilot to switch fuel tanks in time to prevent him from IMMEDIATE CAUSE: running them dry.

UNDERLYING CAUSE: Failure of the pilot to recognize the difference between the loss of power due to propellers sticking in full high pitch and that of running out of gas.

It was carelessness in that the pilot should have switched from reserve to main tanks approximately 15 minutes after take-off and immediately prior to landing switched back to reserve tanks.

(30) RECOMMENDATIONS:

to explain the causes ,.

None.

Each member of the Committee has read and understands A. C. Circular No. 15-14, A. R. 95-120, and N. A. C. A. Report No. 576.

The above statement and recommenda tions, and the classification and analysis shown on the reverse hereof, are the concensus of opinion of this Committee. or, A.C. Operations Officer,
(Rank) (Designation) Member (Designation) Capt., A.C., Ass't Operations Officer
(Rank) Accident Officer

(31) REMARKS AND RECOMMENDATIONS (accomplish only if this report is initiated at other than the home station):

Date Signature ...

(32) REMARKS AND RECOMMENDATIONS:

I concur in the analysis and recommendations of the above Aircraft Accident Classification Committee. The necessary disciplinary action has been taken.

ENCLOSURES (line cut those not applicable): Station Atcham, ETOUSA, Date October 3, 1942.

(Airship) Flight Re

ist of damaged parts.

S, Colonel, Air Corps,

per clippings RESTRICTED

Rg 5429

49TH FIGHTER SQUADRON (TE) ARMY AIR FORCES
Office of the Engineering Officer
APO 637 ETO Usa

October 2, 1942

On September 27, 1942, F-38F A.C. Serial No. 41-7677 made a crash landing on the beach near Llanbedr. The damage by crash landing and salt water was extensive and it will be necessary to salvage the entire airplane.

Lyndon B. VAN HOOK

Engineering Officer

TRESTRICTED"

Juel.#1



000.93

1st Wrapper Ind.

"RESTRICTED"

E-17-3

24)

HEADQUARTERS EIGHTH AIR FORCE, ETOUSA, October 24, 1942
To: Commanding General, Army Air Forces, Washington, D.C.

 Enclosed herswith is Technical Report of Aircraft Accident Classification Committee on 2nd Lt. Robert F. Elliott, Reserve Extended Duty, in P-38F airplane, A.C. No 41-7677

2. Approved.

For the Commanding General:

1 Incl:

Rm #340

A.C. Form #14.

L'RESTRICTED"

SIAR

MOV 20 1042 LLE - NO. ALI

13-2454



000.93

1st Wrapper Ind. "RESTRICTED"

E-17-3

HEADQUARTERS EIGHTH AIR FORCE, ETOUSA, October 24, 1942
To: Commanding General, Army Air Forces, Washington, D.C.

1. Enclosed herewith is Technical Report of Aircraft Accident Classification Committee on 2nd Lt. Robert F. Elliott, Reserve Extended Duty, in P-38F airplane, A.C. No 41-7677

2. Approved.

For the Commanding General:

1 Incl:

A.C. Form #14.



VAR DEPARTMENT HEADQUARTERS ARMY AIR FORCES WASHINGTON

"RESTRICTED"

Received from	*	Headquarters	Army	Air	Forces,
the following	document: Mighth Air Force				

Addressed to: AFDFS

Subject: Technical Report of Aircraft Accident Classification Committee.

Type of Corres.: Letter

Date: Nov. 21, 1942

Basic Dated: Oct. 24, 1942

Number of Incls.:

PIEASE ACCOMPLISH AND Directorate of Flying Safety, Maritime Bldg. RETURN INTEDIATELY TO Room 803

/ CAHALAMAH CAA	184
'/XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Tro.
	IRALALAS TALALAS
	4944 199449 1944,
427716611667	KAHA,
MITTHITATION	₩.

AAF NO. ______

*Insert symbol of office of origin.

BY M. J. Zhyung
Name

Ragik Branch

OFFICE OF: AFOFS