Accident No. 4 Date Checked by\_\_\_\_/ Copied for wright Field by (Mature Crow Take of Groundlooped (49 Control Control (Cause Como Sechnique Thomas Jones Lack more proficiency Colling

## RESTRICTED

WAR DEPARTMENT

U. S. ARMY AIR F

ACCIDENT No.

REPORT OF AIRCRAFT ACCIDENT

(1) Place LLANHEDR 19 May, 1943 (2) Date AIRCRAFT: (4) Type and model P-47C (5) A. F. No. 41-6356, (6) Station AAF F-356
Organization: (7) 8FC - 8AF (8) 4th Fighter Cps 335 Fighter Squadron - 8AF (8) 4th Fighter Cps) 335 Fighter Squadron 145 PERSONNEL NAME (Last name first) Date PERSONNEL CLASS PARACHUTE (11) (10) (12)(13) (14)(15) (16) (17) (18) (19) DI P ELLINGTON, PAUL M. 90 01 P 0-885200 None / 1st Lt. 8FC None PILOT CHARGED WITH ACCIDENT (22) lat Lt.... (20) ELLINGTON (21) 0-885200... Assigned (25) 8FC - 8AF (26) 4th Fi Gp. (27) 335 Fighter Sq. (28) AAF F-356 Attached for flying (29) 8FC - 8AF (30) Ath Fi Gp (31) 335 Fighter Sq. (32) AAF F-356 (34) 21/9/12 Present rating (35) P (36) 21/9/12 FIRST PILOT HOURS: (at the time of this accident) 37:45. (42) Instrume (38) This type..... (39) This model..... 65:05 (40) Last 90 days..... (44) Night tir 280:55.. (45) Night tir (41) Total..... AIRCRAFT DAMAGE DAMAGE (46) Aircraft .... Both wings, fuselage, underfarings Major overhaul. (47) Engine(s) .... Complete Wreck. (48) Propeller(s) (50) Weather at the time of accident

## DESCRIPTION OF ACCIDENT

(Brief Indirative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

It. Ellington started his takeoff with the aircraft headed slightly toward the left side of the runway. The aircraft swerved slightly more to the left and reached the center of the runway about 225 yds. from the start of takeoff, when application of rudder and brake checked the left swing and caused the aircraft to swerve to the right. Pilot was unable to check this swing to the right, which gradually increased until the left landing gear folded inward, the left wing struck the ground, the right landing gear folded outward at an angle of about 45 degrees, letting the aircraft down on its belly; the propeller struck the ground and the aircraft skidded to a stop, facing in the direction from which it came:

Pilot states he was in the habit of taking off with tailwheel unlocked. This had been a common practice among some of the pilots.

Immediate Cause: Loss of directional control during takeoff.

Underlying Cause: Habit of taking off with tailwheel unlocked.

The accident is analyzed as pilot error, 100%, in that the pilot lost directional control during takeoff.

Remarks: Instructions have been issued requiring that the tailwheel be locked for takeoff.

Signature 10 F. LALOUE, 1tCol, AC, Acftacc O.

Date 25 June, 1943.

## RESTRICTED

## PILOT'S STATEMENT:

I taxied into position and started my takeoff immediately. I was headed just a trifle to the left. The aircraft swerved to the left a trifle more, as I started taking off, and I used rudder and brake to turn back to the right. It kept turning more to the right, in spite of all I could do. The left gear folded underneath about the time I left the runway, the wing-tip scraped the ground and the aircraft came to a stop headed back in the direction from which I came.

/s/ Paul M. Ellington
PAUL M. ELLINGTON,
lst Lt, AC,
Pilot.

A TRUE COPY

JULIUS W. TOY, 1st Lt, AC.