Her mountain, 2 miles to of your purchase, Cheshire, England 43-12-3-501 Polat took off with merchelity & miles & certing 1000 ft. He dad no radio + was flying at For fl. I stay contact. He began a climb or instruments into the necessary when he crashed into the side of a mountains. The pilas had knowledge of the weather of hier the ships had no radio. He also knew of the harroge hallan hozard while shirted but as he was off course he want sure just where it was." 1913-X.



Accident No. 43-12-3-50/

Date	Errors	which	change	the	meaning	$\circ f$	the	McBee	Card
Analyzed by Analyzed by Analyzed by	·								•
Typed by									
				• • • •		• • •	• • • •		
Coded by									
eg									
Punched by									
시설하는 아이들은 생기로 들어가 되는 것이다.									
		• • • • • • • • • • • • • • • • • • • •		• • • •		•••	• • • •	• • • • • •	
Verified by									

TECHNICAL REPORT OF AIRCRAFT ACCIDENT CLASSIFICATION COMMITTEE

								Y			
(1) Th	ne Accident	Cla	selfication Committee of	91	590		п	net on 7 December 1942			
	and determ	ined	the following:					0.474 18 1			
(2) Pl	ace, date, a	nd t	ime of accident Hen Mountain, 2 mile								
We	st of L	ORE	erhead Cheshire England at 12/3/h2, 1:05 hrs. mgferd Ledge drg. L.L.A.D. buerd No. 6179					gford Lodge, N. Ireland			
(3) Ai	rcraft stati	onLe	ngford Ledge grg. L.L.A.D.	(1				Res., ext. dutyX Res., inactive			
(4) Ai	rcraft mode	elC	hterd 112 No. 6179					Grad. cadet Student			
			m contractor		Ot	her (speci	ify)				
(6) To	otal hours		Hours since overhaul					7th Air Depet Group			
(7) Er	ngine model	Ch	eetah	(1	9) Org	-attached	d for f	flying Langford Lodge Air Depot			
(8) Er	ngine A. C.	No.	8	(2	20) Regu	lar duties	assig	ned Operations Officer			
L.	0	. L	I. None. R. I. None. R. O.								
(9) Ex	tent of dar	nage	to engine(s)) (2	21) Origi	nal pilot	rating	and date April 29, 1942			
L.	0.	L	I. None R. I. None R. O. A.	· (2	22) Total	l pilot ho	urs	600 Hours on this model .90			
(10) To	otal engine	hour	8					st'3 months 100			
L.	0	_ L	I None R. I None R. O.		(1)	20		(2) 40 (3) 40			
(11) Er	gine hours	sinc	e overhaui	,				(1) Oxford			
L.	0	L	I None R. I None R.O. Return Flight to Langford aft delivery of Radio Equipment.	(2	24) Mode	els flown	last 3	months (2) P-38			
(12) Pu	irrose of fli	ght	Return Flight to Langford aft	er				(3) C-19			
(13) To	ook off from		A Airdrens A Time 1345	(2	25) Secur	re from F	light	Surgeon, it phot error is a causal factor:			
(14) W	eather at ti	ma	raccident. (If weather was a causal factor	,-				hysical or neuropsychic condition which			
	and the second second second		weather report and forecast for the flight.)		wo	uld in any	way :	account for this accident? Yes or No. No.			
			500 ft. or less. No visibilit	y	the ex	trabic		그 마다 그 아이는 그 그는 그는 그는 그 그리고 있었다. 그 그 그리고 있는 그리고 있다.			
			at site of accident.	(2	26) Dam	age to pri	ivate j	property; Yes or No No form No. 17, "Damage to property certificate."			
(27) ==	.xxxxan		AV JAVV VA HERMINIST		11-1	es", attach	A. C	form No. 11, Damage to property certificate.			
(2.)		RI	SULTS TO PERSONNEL		%	%	%	CAUSES COLUMN			
				П		DET	de	Barrella A / /2 /2			
	C-Comman	UMN .	N-Navigator B-Bomber	3	4.00	1/3/1	-	Error of judgment,			
	P-Pilot		R-Radio operator O-Other crew	4		PILOT		Poor technique,			
DUTY	CPCo-pile OBObserv	rer	R-Radio operator O-Other crew E-Engineer PH-Photographer Army status, as; Regular Army, Res. ext., Res. inact., etc.	1	DPD	ERROR		Disobedience of orders,			
	Name, rank.	and	Army status, as; Regular Army, Res. ext., Res. inact., etc.	Used	PER-	~		Carelessness of negligence,			
Andrew College Comments of the College Comments of the College				5	ERROR	3		Miscellaneous,			
X J. L. Pe		Pea	rce, 1st Lt., Sig. Cor.		01	OTHER		Supervisory personnel,			
			AUS 98 X		11 8	SONNEL		Maintenance personnel,			
1P	Joseph	E.	Lowe, 2nd Lt., A.C.,		A			Other personnel,			
		200	Res. Ext. duty X	13			П	Fuel system,			
				13				Cooling system,			
			FEB 1 43 AM 0/					Ignition system,			
			- L				1	Lubrication system,			
						POWER		Engine structure,			
-						PLANT	H	Propeller and propeller accessories,			
	***************************************							Engine control system,			
	a c. tradit - c. parti - commentation - alivent - c c. e contra-		9: 10: 5		/	1		Miscellaneous (specify),			
			(a) /(4/								
			2			-	1	Undetermined,			
-				1			\vdash	Flight control system,			
		-	RECEIVEL				1	Movable surfaces,			
			HG. AAF., DIRECTO	T	MATE-			Stabilizing surfaces; struts, wires, and fittings,			
			OF PLYING SAFET	+	RIEL		-	Wings; struts, wires, and fittings,			
	L		parachute jump by attachment)	Н			-	Landing gear; struts, wires, fittings, and retract, mech.			
(Exp	and any unsuc	COGNIC		L		CRAPT	1-1	Wheels, tires, and brakes,			
			NATURE (Check one only)		/	CRAPT STRUC TURE	-	Fuselage, engine mount and fittings,			
		_	A-Collisions in full flight with good aircraft,	10	1		-	Cowling, fairing, and fittings,			
DAMAG	E TO AIRCR	APT		-			-	Tail wheel assembly and skid,			
(Le	es power plant)	,	B—Collisions in full flight with object ther their perman	W	200		-	Miscellaneous (specify),			
			C-Spins or stalls following engine failure,	-			1 1	Miscenaeous (specify)			
			D—Spins or stalls without engine failure,	_			-	Foldering Value			
A-Com	lete wreck,		E (1)—Emergency forced landings,				+	Undetermined,			
		X	E (2)—Deferred forced landings,	_			-	ling qualities,			
B-Wales	r overhaul,		F—Landing accidents,				Instruments,				
B-major	· Overment,		G—Take-off accidents,				Misce	flaneous e uipment (specify),			
C-W-1	r replacement,		H-Taxing accidents,			20	10	65 36 36			
	epiacement,		I (1)—Fires in the air,			-	Weat	her. 33 85 31			
			I (2)—Fires on the ground,		CELLA-		Dark	Dess.			
D-Mino	or damage,		N-Structural failure,		NEOUS		Airpo	ort or terrain,			
			X-Miscellaneous,				Other	•			
E-No di	amage,		Y-Undetermined,				Unde	termiped,			
					~		Anna spends	220			
			Mel H & Mapes	a(CLE	,		220			
33	51		MIH W		_						
			merco	-	,						
								교실하는 사람이 내려가 하는 사이들은 경상을 하는 것이다.			

RESTRICTED

(28) PILOT'S STATEMENT (state how the accident occurred, giving all details as to conditions, causes, and influencing factors);

Received weather report from Speke before taking off. giving 1500 ft. ceiling and 2 mile visibility. After taking off, crossed River Mersey to Hootenpark Airport, took up 280° heading which should have brought me to the coast in about 10 minutes. Had no radio and I tried to stay contact below 800 ft. Seeing trees immediately below me while flying partially on instruments I began to climb up into the evercast. Had not previously climbed higher because of no radio and also an icing level of 1500 ft. or less. In two or three minutes after I started climbing on instruments the accident occurred.

I made no 160° turn because of nearby barrage balleons over Liverpool and the surrounding area. I flew a 280° course allowing for an approximate 10°

variation which would give me a true course of 270°.

Signature ... JOSEPH E. LOWE, 2nd Lt., Pilot.

(29) STATEMENT OF ACCIDENT CLASSIFICATION COMMITTEE (give complete causal statement, amplifying the pilot's statement where necessary to explain the causes):

This accident was caused by pilet being off his course due to peor visibility and while flying by instruments struck side of mountain. The aircraft was not equipped with receiving radio. Ship had been salvaged by British crew on orders of Flight Officer Wallis of Sealand Airdrome who had already submitted a complete report to British Air Ministry.

Error of judgement as charged against pilot was probably produced almost entirely by fear of balloon hazard which he knew existed at a then unknown

distance to the North.

(30) RECOMMENDATIONS:

Reccommend that consideration be given to grounding barrage balloons in this vicinity except when immediate danger of attack by enemy aircraft is known to exist, and that a system be devised whereby our pilots could be advised when

balloons are down (as is done by Manchester authorities).

Each member of the Committee has read and understands A. C. Circular No. 15-14.

A. R. 95-120, and N. A. C. A. Report No.

The above statement and recommenda-tions, and the classification and analysis shown on the reverse hereof, are the concensus of opinion of this Committee.

Signed Commun

(31) REMARKS AND RECOMMENDATIONS (accomplish only if this report is initiated at other than the home station):

Opinion of Aircraft Accident Classification Committee concurred with.

Station AAF 590, APO 635 Date Dec. 26, 1942 Signature

(32) REMARKS AND RECOMMENDATIONS:

W. M. Colonel, A.C., Commanding

our with findings of consittee.

Enclosures (line cut those not applicable):
Airplane (Airship) Flight Report.
Unsatisfactory Report. Photographs. Certificates of principal witnesses.

List of damaged parts.

ewspaper clippings.

Damage to property certificate, A. C. Form 17.

Stationia VIII APSC, APO 633, AAY STA. Date 30 Dec. 1942. 586

For the Commanding Coneral:

Signature

Commanding.

RESTRICTED

Reproduced by Headquarters SOS ETO USA HQ-808-9-42/IM/220

HEADQUARTERS, VIII AIR FORCE SERVICE COMMAND, APO 633. 15th. December 1942. TO: Commanding Officer, AAF Station No. 590, APO 635, U.S.A.

- 1. Aircraft Accident Classification Committee Forms 14 are returned for re-consideration by the Committee and completion of item 32.
- 2. It is difficult to understand the findings of 25% pilot error and 75% weather, under circumstances wherein the pilot had knowledge through weather reports of the conditions expected en oute as well as the presence of smoke haze, the barrage balloon hazard and the lack of radio facilities in the aircraft.
- 3. The forms should be returned to this Headquarters after compliance with the instructions contained in par 1 above.

E

By Command of Brigadier General MILLER:

B. L. DAVIS, Colonal, A. G. D., Adjutant General,

Incl: n/c

DEC 3 A)

3rd Ind.

H-1-w

HEADQUARTERS, AAF STATION 590, APO 635, U. S. ARMY - 26 December 1942. TO: Commanding General, VIII Air Force Service Command, APO 633, U. S. Army.

191. 2nd Indorsement complied with.


- 2. The opinion of the Aircraft Accident Classification Committee is set forth in par 2 of accompaning letter signed by the chairman thereof.
 - 3. This opinion is concurred with



OC 28 1942

W. M. LANAGAM Colonel, A.T., Commanding.

Incls: n/c
Added: Letter- Major W. C. Buell.



COPY No OF THE REG. INDEX No.3151

11 December 1942

Technical Report of Aircraft Accident Classification committee. SUBJECT:

Commanding Officer, Station 590. TO

1. Submitted herewith is Air Corps Form Ne. 14 submitted in quadruplicate as required by A.C. Circular 15-lh for accident of December 3. 1942 in which Oxford type Airplane No. British 6179 was involved.

- 2. Following required enclosures to report were emitted for reasons shown:
 - a. Flight report -- Destroyed with aircraft.
 - b. Photographs-None available-Complete wreck.
 - c. Unsatisfactory Report -- No materiel failure.

WILLIAM C. BUELL,
Major, A.C.,
Chairman.

Encl:

1. A.C. Rorm 14 - 4 copies

2. Weather Report - 4 cepies

1st Ind.

H-3-9

HEADQUARTERS, AAF STATION NO. 590, APO 635, USA, 12 December, 1942. TO: Commanding General, VIII Air Force Service Command, APO 633, USA.

1. The inclosed report of the Aircraft Accident Classification Committee is submitted in accordance with Army Regulations and with instructions issued by the Chief of the Air Corps.

ECEIVO Commanding Officer:

Captain, A.C.,

Adjutant.

VIII A. F. S. C

COPY No... REG. INDEX No 335

Inol's - n/e

AIRCRAFT ACCIDENT CLASSIFICATION COMMITTEE STATION 590 APO 635 ETOUSA

24th December 1942

SUBJECT: Technical Report of Aircraft Accident Classification committee.

TO: : Commanding Officer, Station 590.

1. Reference to 2nd indersement from Adjutant, VIII AFSC, 15 December 1942, the Aircraft Accident Classification Committee has met and reconsidered the circumstances attendant upon crash of the Oxford No. 6179 on 3 December 1942.

2. The presence of feg and smake haze with limited visibility, and balloen hazards at the time this pilet left Spake were fully considered by the board. The weather forecast for the greater part of the trip, including areas near proposed landing place, was very good; weather at points near take-off were known to be less than good, but to delay all flying until weather reports show good flying conditions at all points along any proposed route in the British Isles, would seriously impair the flying program which is considered necessary if this Command is to meet the demands being made upon it. The purpose of this trip was to transport certain signal equipment. Consequently, the Board did not consider the pilet at fault as to the take-off under conditions then existant; but the Board did consider his subsequent handling of the plane after weather deteriorated, as faulty. The proper action would have been to attempt to return to the starting point, or to the airdome at Scaland. The percentage of 25% charged as pilet error was for that failure, and not because he took off under less ideal weather conditions.

3. The Committee respectfully reiterates its findings as shown on Ferm 14.

William C. Buces

William C. Buell Majer A. C.

Operations Officer

Chairman.



COPY No OF 3 REG. INDEX No 337/ ECRET

A TRUE COPI

AIR MINISTRY, METROROLOGICAL OFFICE.

LATEST REPORTS of WEATHER (QAM) on

Time Station Of Observa Name	HEINE	General Weather		F	how Cloud		Tota1	Wind at the		Past Weather		
	Name	M.S.L. (moter)	and Warnings	Visibility	Form of Cloud	THE STATE OF	low Close	Cloud		Speed (Km./km	Description	Person
300 400 500	SPEKE	was carrier of some facility of facility of	slight mist misty misty	2,200 yds 2,000 yds 1,800 yds		4100 ft 3000 ft 3000 ft	10/10	10/10 10/10 9/10	Bbys SE	5 mph 5 mph 5 mph		
300 400 500	SRALAND		elight mist slight mist slight mist	2,200 yds 2,200 yds 2,200 yds			10/10	10/10	258 53 52	5 mph 3 mph 5 mph		
enera ere g	Aan. Tuiolms	eather or tion of d	ver Ireland was made at liffuse warm front over sea level) F.L. 1500 f intermittent elight rain	t with severe	ring intermity	dnt dris	ale or	sleet,	ith patc	nes		
		A STATE OF THE STA		Total man o		COUU I	E 9/10	10/10	H. 1	10 mph		
	Ballyralbert Ramsey		cloudy choudy	6 mls 4 mls		2500 f 2500 f 3500 f	5/10	10/10 10/10 9/10	ESE ES	10 mph 10 mph 10 mph		
evere 300	RANSBY		clesty	6 mls	naldsway give locally with	2500 f 3500 f	9/10 9/10 ed war loke ha	9/10	ESE E/S	10 mph 10 mph		
300 3 ¹⁴ 5	RAMSEY icing and patc RAMSEY ROHALDSWAY	ches of c	cloudy cloudy leud 800 ft; visibility cloudy	6 mls 4 mls 4 mls Subsequently 4 mls 2 mls	locally with	2500 f 3500 f m; repeat thick si 6,000f	9/10 9/10 ed war loke ha	10/10 9/10 sing above near 5/10	ESE E'S ut Liverpee SE	10 mph 10 mph 1.		

1st Wrapper In

E-Q-9

HEADQUARTERS EIGHTH AIR FORCE, 3 January 1943. TO: Commanding General, Army Air Forces.

- l. Transmitted herewith are Technical Reports of Aircraft Accident Classification Committees relative to the following accidents:
 - a. 2nd Lt. Richard J. Drayton in a P-400 aircraft No. AH-609.
 - b. 2nd Lt. J. E. Lowe in an Oxford aircraft No. Br. 6179.
 - c. Lt. John A. McLean in a B-17F aircraft No. 124451.
 - d. Capt. Robert A. Patterson in a Tiger Moth aircraft No. DE-560.
 - e. Capt. Walter W. Berg in a Spitfire V-B aircraft No. EN-839.
 - f. 2nd Lt. D. W. Koon in a Spitfire aircraft No. P-7906.
 - g. Maj. Joseph M. Cole, Jr., in a Miles Master aircraft No. DL-679.
 - 2. Approved.

For the Commanding General:

7 Incls:

Incl 1 - Form 14 and allied papers (Drayton).

Incl 2 - Form 14 and allied papers (Lowe).

Incl 3 - Form 14 and allied papers (McLean).
Incl 4 - Form 14 and allied papers (Patterson).

Incl 5 - Form 14 and allied papers (Berg).

Incl 6 - Form 14 and allied papers (Koon).

Incl 7 - Form 14 and allied papers (Cole).

RESTRICTED"

CONFIDENTIAL

R-252

1

JAN 27 1843

JAMES B. GORDON.

Lt Col, AGD,

Asst Adj Gen.

40336

1st Wrapper Ind WSIRICIFO

E-Q-9

HEADQUARTERS EIGHTH AIR FORCE, 3 January 1943. To: Commanding General, Army Air Forces.

- l. Transmitted herewith are Technical Reports of Aircraft Accident Classification Committees relative to the following accidents:
 - a. 2nd Lt. Richard J. Drayton in a P-400 aircraft No. AH-609.
 - b. 2nd Lt. J. E. Lowe in an Oxford aircraft No. Br. 6179.
 - c. Lt. John A. McLean in a B-17F aircraft No. 124451.
 - d. Capt. Robert A. Patterson in a Tiger Moth aircraft No. DE-560.
 - e. Capt. Walter W. Berg in a Spitfire V-B aircraft No. EN-839.
 - f. 2nd Lt. D. W. Koon in a Spitfire aircraft No. P-7906.
 - g. Maj. Joseph M. Cole, Jr., in a Miles Master aircraft No. DL-679.
 - Approved.For the Commanding General:

7 Incls:

Incl 1 - Form 14 and allied papers (Drayton).

Incl 2 - Form 14 and allied papers (Lowe).

Incl 3 - Form 14 and allied papers (McLean).

Incl 4 - Form 14 and allied papers (Patterson).

Incl 5 - Form 14 and allied papers (Berg).

Incl 6 - Form 14 and allied papers (Koon).

Incl 7 - Form 14 and allied papers (Cole).

a RESTRICTED"

JAMES B. GORDON.

Lt Col. AGD,

Asst Adj Gen.