DATE RESTRICTED WHEN ENTRAES WADE ACTION FORM I 4A RECEIVED (BEVISED 1 JAN 45) 76, ARMY AIR FORCES EVALUATED BY 00 18-17 REPORT OF MINOR ACCIDENT VERIFIED BY Use this form for minor accident only in accordance with AAF Reg 62-19, and "Aircraft Accident investigator's Handbook," Reg 62-19, and "Aircraft Accident Investigator's Handbook," Issued by Office of Flying Safety. Under Section B, "Accident Data," minor injuries and/or minor damages are those as de-CHECKED BY 0 NO. AIRCRAFT CODED BY fined in the above regulation. NYOLYE SECTION A-IDENTIFYING DATA (I) PLACE OF ACCIDENT - STATE - COUNTY - NEAREST TOWN - DISTANCE & DIRECTION FROM SAME | NEAREST ARMY AIRFIELD - DISTANCE & DIRECTION FROM SAME In flight 100 Miles SE of 1407th AAF Base Unit EURDATC (2) MAS COLLISION WITH OTHER AIRCRAFTT (3) AF NUMBERS OF AIRCRAFT INVOLVED (FILE SEPARATE FORM I MA FOR EACH AIRCRAFT DATE HOUR & TIME ZONE B-17 @ 43-37975 X YES B-176 43-38704 17302 8/7/45 X (4) AIRCRAFT NO. (5) TYPE MODEL SERIES (6) HOME STATION 43-38704 LAVENHAM B-17 G (7) AIR FORCE OR COMMAND SUB-COMMAND GROUP - NO. AND TYPE SOUADRON 487 Bombardment Sth AAF lat Biv 839 (8) OPERATOR (LAST NAME, FIRST NAME, INITIAL) GRADE TOTAL PILOT TIME BRANCH AGE (9) MORMAL DUTY STATUS SEX Gerand, Learence J M Pilot lst Lt AF OR COMMAND SUB-COMMAND GROUP - NO. AND TYPE SOUADRON 8th AAF 487 Bombardment lst Biv 839 Transient SECTION 8 — ACCIDENT DATA

(i) DESCRIPTION OF ACCIDENT (INCLUDE HISSION) 2-17 \$43-38704 and \$43-37957 were in a flight of 32 aircraft being ferried from Levanham to Valley few redeployment to the some of interior. The flight departed from Levanham with a one (1) minute take off separation. The pilots had been priefed to fly at 6000ft at which altitude there was 5/10th cumulus clouds. This was not a formation flight. About 100 miles south east of Valley both aircraft emerged from a cloud with B-17 \$43-37975 directly above B-17 \$43-38\$04 in very close preximity. Both pilots took evasive action, At this point the bottom of the tail terret of B-17 \$43-37975 made contact with the top of the vertical stabilizer of B-17 #43-38704 causing slight damage to both aircraft. The flight was continued on to Valley without incident. No change in flying characteristics was noticed in either aircraft. (2) PERSONNEL INVOLVED, NAME, GRADE, BRANCH, ASN, HOME STATION, EXTENT OF INJURY No injuries. (3) EXTENT OF DAMAGES - AIRCRAFT AND/OR OTHER B-17 6 43-38704 Six inches on the top of the vertical stabilizer bent over B-17 6 43-37975 Skin dented on bottom of tail turret. (4) CONTRIBUTING CAUSE FACTORS Pilots flying instruments intermitently when take-off separation was intended for contact flight. REPORTING STATION 1407TH AAF BASE UNIT 0一片883种种 Captain

if necessary)

RESTRICTED

PEADQUARTERS

1407TH AAF BASE UNIT

EUROPEAN DIVISION, AIR TRANSPORT COMMAND
APO 741

c/o PM NEW YORK, NY

OPS/JDR/mmc

360.33

14 July 1945

SUBJECT: Transmittal of Report of Minor Accident, AAF Form No. 14A.

TO : Commanding General, AAF, Winston-Salem, N. C. Attn: Chief, Flying Safety.

1. Transmitted herewith Report of Minor Accident, AAF Form No. 14A for B-17G 43-38704.

For the Commanding Officer:

JOYCE C. MENT, let Lt, Air Corps, Adjutent.

Incl: AAF Form No. 14A

DISTRIBUTION:

Commanding General, AAF, Winston-Salem, N. C. Attn: Chief, Flying Safety. Commanding General, Hq. 8th Air Force, AAF Sta. 101. APO 633, U.S. Army. (thru channels) Medical Officer, 1407th AAF Base Unit, European Division, ATC, APO 741, U.S. Army.