

*Harold's Barn, Chapel Barn
& The Cider Press*

Barns at Court Farm, Trellech

Photographic Survey

This photographic record refers to three barns situated at Court Farm, Trellech, /Monmouth, NP25 4PE.

The planning application numbers for the properties are:

DC/2007/01673

M/10739

DC/2010/00899

The following has been taken from Historic Building Condition Database.

Location

The barns are located immediately to the west of Court Farmhouse, Trellech, Monmouth, NP25 4PE.

History

The barn incorporates a probably late C16 stone archway and window which seem to suggest a domestic origin for a part of the building. The barn itself is late C17 or early C18 and has a corrugated metal sheet roof which was put on after it was bombed in WWII.

Exterior

The barn itself is built of squared stand-stone rubble with a corrugated sheet metal roof. It is in two builds with the larger part to the south. The south gable has two slit vents with another in the gable above. At the north there is a 4-centred arched stone entrance which is probably late C16 or c1600. Beside it is a 2-light window with a reserved chamber. Adjoining this to the right is a small C19 stable and granary with a corrugated sheet roof.

Interior

There is a queen strut roof with two tiers of purlins and rafters at the south end, with at least three trusses surviving. The north end of the roof, where it was hit by a bomb, has machined king post trusses with iron straps which were put in c1943.

The barn is listed primarily for its group value with the adjacent Court Farmhouse.

Barn 1
Harold's Barn

Barn 1 – Harold’s Barn
External Photographic Record
East Elevation
B1EE1 – looking down the yard



B1EE2 – looking up the yard



B1EE3 – face on



South Elevation

B1SE1 – East elevation corner taken into account



B1SE2 – west elevation corner taken into account



West Elevation

B1WE1 – overview



B1WE2 – face on



Internal Photographic Record

North Elevation

B1IN1 – gable stonework



B1IN2 – top of gable



East Elevation

B1IE1 – barn door and wall running up to north gable



B1IE2 wall running to south gable



B1IE3 – slit window (closer to north gable end)



B11E4 – 2nd slit window




B11E5 – 3rd slit window



B11E6 – 4th slit window



B1IE7 – 5th slit window



B1IE8 – barn door face on



South Elevation
B1IS1 – face on



B1IS2 – bottom arrow slits



B1IS3 – top of gable



West Elevation

B1IW1 – doorway next to the south gable



B1IW2 – central slit window and barn door



B1IW3 – Barn door and slit windows next to north gable



B1IW4 – central slit windows face on



B1IW5 – face on slit windows nearest north gable



Timber

B1MT1 – main trusses looking south



B1MT2 – main trusses looking north



B1MT3 – Truss nearest north gable



B1MT4 – second truss



B1MT5 – third truss



B1MT6 – fourth truss



B1MT7 – fifth truss



B1MT8 – sixth truss nearest south gable



Barn 2
Chapel Barn

Barn 2 – Chapel Barn
External Photographic Record
North Elevation
B2NE1 – situation next to Barn 3 (B3)



B2NE2 – face on



East Elevation
B2EE1 – face on



B2 EE2 – situation next to Barn 1 (B1)



West Elevation

B2WE1 – together with north elevation



B2 WE2 – situation next to B1



Internal Photographic Record

North Elevation

B2IN1 – gable end stone work



B2IN2



East Elevation
B2IE1 – overview



B2IE2 – arch doorway



South Elevation (internal wall)
B2IS1 – stonework



B2IS2 – stone wall in relation to barn doorway



West Elevation
B2IW1 – overview



B2IW2 – arch window




Timber
B2MB1 – main oak beams



B2MB2 – main beams close up



B2MT1 – Main truss next to east elevation



B2MT2 – main truss next to west elevation



B2RT1 – roof timber overview



Barn 3

The Cider House

Barn 3 – The Cider House (formally *The Granary*)

External Photographic Record

North Elevation
B3NE1- overview



B3NE2 – situation next to B2 (Barn 2)



B3NE3 – back of store room



East Elevation
B3EE1 – overview



B3EE2 – face on



South Elevation
B3SE1 – overview and situation next to B2



B3SE2 – face on



B3SE3 – main entrance stone work



B3SE 4 – second entrance closes to the west elevation



West Elevation
B3WE1 – face on



B3WE2 – external steps



Internal Photographic Record
Ground Floor
B3GF1 – north elevation window



B3GF2 – north elevation door



B3GF3 – store room back wall



B3GF4 – east elevation wall



B3GF5 – stairs and south elevation window



B3GF6 – south elevation main door



B3GF7 - west elevation back wall



First Floor
B3FF1 – north elevation window



B3FF2 – east elevation gable and wall and truss




B3FF3 – south elevation window closest to store room



B3FF4 – south elevation window closet to west elevation



B3FF5 – west elevation doorway



B3FF5 – west elevation gable wall



Timber

B3MB1 – oak main beam nearest west elevation



B3MB2 – oak main beam nearest east elevation



B3MT1 – main truss nearest west elevation



B3MT2 – main truss nearest west elevation in relation to oak beam



B3MT3 – main truss nearest east elevation

