




Photographic Schedule of North Wales Hospital




for

Denbighshire County Council ,
Smithfield Road,
Denbigh ,
LL16 3RJ

Ref: 168119/ Main Range Elevation F

Date of Inspection: 28th Sep 2018

Ref	Photo	Comments
1		Elevation F 4 bays
2		Bay 1 roof destroyed by fire
3		Bay 1 damage to pediment, roof destroyed by fire.

4		Bay 2 Turret destroyed by fire
5		Bay 3 due to vegetation hard to identify all defects
6		Bay 3 no roof due to fire

7		Bay 3 smoke damage
8		Bay 4