




# Photographic Schedule of North Wales Hospital




for





Denbighshire County Council,  
Smithfield Road,  
Denbigh,  
LL16 3 RJ




Ref: 168119/Nurses Home Elevation A

Date of Inspection: 28th Sep 2018

Ref	Photo	Comments
1		Elevation A 6 Bays
2		Bay 1
3		Bay 2

4		Bay 3
5		Bay 4
6		Damaged parapet above entrance bay. Of bay 4

7		Bay 5
8		Bay 6
9		Dilapidated bay window to bay 6
10		Structural movement and missing pointing to single storey of bay 6

11		Valleys stripped on both sides of pediment
12		
13		
14	