




# Photographic Schedule of North Wales Hospital




for

Denbighshire County Council,  
Smithfield Road,  
Denbigh,  
LL16 3RJ

Ref: 168119/Chapel Elevation A

Date of Inspection: 28th Sep 2018

Ref	Photo	Comments
1		Elevation A
2		Structural cracking right side lower corner of window
3		Minor movement of copings

4		
5		Aerial of roof
6		
7	